


Introduction


SPC Office Buddy is a revolutionary application that integrates directly with Minitab, JMP, and Microsoft Excel to run reports using inspection data collected by QC-CALC Real-Time. Statistical reports or Sixpacks can be run on any subset of data and placed into Excel reports. Buddy automatically sends each characteristic's label, nominal, tolerances, and subgroup information straight to Minitab or JMP without typing, saving you time and money.



Excel Jobs

QC-CALC is the leader in data collection and Real-Time SPC, Minitab is an industry leader of 6-Sigma statistical software, and Excel is the industry standard in spreadsheets. In recognition of these facts, Buddy was written to tie these "best-in-class" products together into a simple, easy-to-use, comprehensive reporting tool to save time and money.


Unlike a typical export, where the data is dumped starting at cell "A1", Excel Jobs can create custom reports in minutes without using macros. They can be created to handle periodic weekly or monthly reports, such as PPAPs, saving time on repetitive tasks. Complex reporting is reduced from hours of needless cutting, pasting, and typing to mere seconds.



Key Benefits

S/FN/SJAC9102 Rev & First Article In

- No more manually entering tolerances into Minitab
- No more Excel macros
- Data is sent directly to Minitab or JMP
- PPAPs or other custom Excel reports are created in seconds using existing Excel reports
- Multiple reports can be run in scheduled batches for full automation
- Fully automated Non-Normal data identification using Goodness-of-fit tests
- Excel Job automation from QC-CALC Real-Time or ERS
- Direct raw data export to Excel, Minitab, or JMP



No.	342								2. Pert Name	Sample		2. Serial Nu	au 34;	4. FAIRs	port			
			Characteristi	c Accou	untability			_			Inspection	_	-	Te	st Results	-1		
No.	6. Ref Location	7. Characteristic Designator	Feature Na		8. Rec	Nominal	Upper	Lower	10. Designed Tooling	11. Non Conformance Number	Inspection 14a. FAI inspection Measuring	14b. Production Inspection	Mc. FAI Inspector Adestificatio	9. Result	,			
	NA		X Hole Positi			1.00000	1.00100	0.99900			Visión		Laura	0.95				
	N/A N/A		Y Hole Posti Z Hole Posti			2.00000	2.00200	1.99800		-	Vision	-	Laura	1.95				
	NA		Line Length	n		3.00000	4.03400	3,99600			Vision Vision	-	Loura	2.95				
	N/A		Oatum 1	_		5.00000	5.00500	4.99500			Valor		Laura	5.00				
	NA		Oatum 2			6.00000	6.00600	5.99400		-	Vision	-	Laura	6.00				
	NA	-	Oatum 3 Oatum 1 - De	hand		7.00000	7.00700	6.99300			Vision Vision	-	Loura	7.00				
	NA		Chanfer An			9.00000	9.02900	8.99100			Vision		Loura	9.00				
	78/4		Seat Dia	_		10.00000	10.01000	9 99000		-	Vaint	-	LAIFA	10.00				
	N/A N/A		Overall Leng Ring length	<u>*</u>		11.00000	11.01100	10 90900		-	Vision	+	Laura	10.95				
	NA		Thread Pitch			13.00000	13.01300	12.98700			Vision		Laura	12.95				
	NA		00 F#			14.00000		13.96600			Vision		Loura	14.00		870		
	N/A N/A	-	Functs Band t							INSPEC								
14			MarDi				C	ompany A	BC, LLC.12	345 EXAMPLI	E AVENUE	N. NEW YO	RK, NY 100	16 (123) 456-7890			
18	NA		ManDi Sup	pler:	INTEL		Part Descrip		Part Numbe	r: 1 16	Revision Level 33	E Da	te Submitted: 12/12/199		ate Needed		Date Finished:	
	NA		× Hole Mater	ial #:	INTEL		54	mple	Material De		33	Lo			fold:	342	Employee #	
20	NIA re Indicete	is that all charac					First Art	icle inspect	00:	- 1	Criticals 0	ely:		-	Revis	sion Dimen	sions Only:	-
berec	By.		_	\$	Samples Per	_	Capabi	ity Study:			Criticals P	us Revision:		0	Ild Revision:	Ne	ew Revision:	_
			TRO	E:O#		j	Customer To	(explain) :	Modification	n Teoling	E	xplanation:				_		
			_	-		1	New Toolog Repair Tools		Process CI	nanged		-			-	_		_
			-	m		t Dim.	Nominal		USL		1	Sample Nur	mber 3	4	5	_	Pass	Fail
				sm	Print	Um.	Nominai	LSL	USL		1	2	3	•	2		Pass	Pan
				1		um 1	5.0000	4.9950			5.0008			9971	5.0004			
				2		- Datum2	6.0000	5.9940			6.0046			0036	5.9960 8.0023	-		<u> </u>
			1. 10	4	Date	um 3	7.0000	6.9930	7.0070		7.0021	6.9954	7.0010 7	0039	7.0043	_		
				6		Position	1.0000	0.9990			0.9991			9986	1.0003	_		
				7		Position	3.0000	2.9970						9975	2.9989	-		-
				8		Length	11.0000	10.989	11.0110		10.9978	11.0012 1	1.0024 11	0046	11.0001			
				9	Ring	length er Angle	12.0000	11.988 8.9910			11.9967 9.0011			.9965 9987	11 9989 9.0029			-
			5.33	11	Snaj	p Dia	10.0000	9.9900	10.0100		10.0014	9.9931 1	0.0007 9.	9962	10.0039			
				12		Fit	14.0000								14.0024	_		-
				13		nal Size	15.0000	14.985 15.984							15.0027	-		-
				15	Line L	Length	4.0000	3.9960	4.0040		4.0018	3 9990 4			4 0013			
				16	Threa: ManDim	d Pitch	13.0000	12 987			12.9990			9986 4900	13.0020	_		<u> </u>
				18		nension 2	2.5351	1.5624			2.4700				2 9500	_		-
						osition x 2		1.9957							2.0005	_		
			- 2	10	Y Hole Pi	osition x 2	4.0000	3.9903	4.0097	-	3.9991	3.9989	1.0034 3.	9972	3.9971	_		-
			-						Please of	complete app	proval and	return via f	ax 123-456-	7890				
nr	any I	Name	0.09	omer	Approva	15												
	nd Print Re			-												-		
	Lot	# 1		Oate		12/12/1994												
_	Operato	SOUTH																
_	Locatio	Adjusters, UEA														-		
Lat	Icol	X Hole PorY Ho	le Por Z Hole F							ta Overall Le Ri 50 11			Functional Bond	56 5	imer Fails			
1	i.	0.999	2 002 3 0 1 998 2 9	17	4.004 5 3.996 4	005 6.00 996 5.55		8.000 7.992		01 11.011 99 10.909	12 012 13 11 588 12	013 54.014 587 13.586		006 2.81 984 0.22	4599 8501			
	_	1 0009 3	0002 3.00 9996 3.00	11 4	4 002 4 5	9957 6.002 0028 6.001	5 7 0007	7.9993	8.9921 3.9 8.9916 10.0 9.9921 3.0	920 93.9951 041 93.9954	11.998 12.5 12.0028 12.5	978 13 9947 963 13 9933		2954 2954	1.90			
=		0.0001 0.0000 0.0000	99996 3 00 99996 3 00 9980 3 00 9980 3 00 9980 3 00 99805 3 00 99805 3 00		6000 A	ATT 6.000	9 7.0087 6 7.0007 5 6.9991 9 6.9991 9 6.9991 6 7.0000 9 7.0000	7 9945	9.0055 13.0 9.0055 13.0	951 90.9964 22 90.9968 229 90.9962	11.998 12.5 12.0028 12.5 11.9999 13.0 11.9965 12 11.9973 13.0	025 13.9997 946 13.9997 957 54.0129	14 9878 15 15 0061 16 14 9917 15		152 163 12	1		
-		0.9998	0002 2.99 0003 3.00 9998 2.99	11 4 19 3	10002 5.0 19992 5.0 3.999 4.9	0003 6.000 0006 6.000 9977 5.965		8.0015 8.0016	9.0064 10.0 9.0077 3.9 8.9935 9	552 90.9925 996 90.9921	11.9992 13 12.0053 12.5	003 14 0024 055 13 9974	15.0031 16 14.9965 15 15.0046 16	992	1.13			
-	_	0.9996 1	39998 2.99 39991 3.00	06 3	3.999 4.9 9996 5.0	977 5.997 9343 6.000		8.0051 8.0017	8 9935 9 9 0014 9 9 8 997 9 9	999 11.0053 549 11.0013 984 50.9834	12:0065 11:0 11:9893 13:0		15.0046 16 14.9943 15	00/9/ 9974				
	_	0.9996 0.9998 1.0005 0.9993	2 2.99	11 4	9996 4 0017 51 5973 4.9	9043 6.000 978 6.979 8003 6.000 9301 6.994	2 6,9989 6 6,9989 9 6,9960 5 7,0000	8.0017 7.9296 8.0011 8.0029	9.0043 93	954 90 9934 854 11,0027 855 11,0008	12 0065 13 0 11 9893 13 0 11 9934 13 0 11 9941 13 0 11 9961 13 0 12 0009 13 0	11 11 11	16 08021 18	4	1.52 1.57 1.47 1.82			
	_	8,7729	0004 3.00 0008 3.00 7201 2.77	5 4	10007 4 9	1966 6006 1974 3.778		8.000 7.3296 8.0957 7.9945		42 93 9964 734 77 77 7712	11 9906 13.0	112 14 0038 121 13 9929 012 13 9929 012 13 9983 015 13 9983 016 13 9983 017 13 9985 017 14 14 14 14 14 14 14 14 14 14 14 14 14	14.9871 16 15.0002 15 14.994 13 15.0008 15 15.0008 15 14.9993 16 14.9993 16 14.9993 16 14.9993 16 14.9991 15 14.9993 16 14.9993 16	9919				
-		4.9997 3.9991	3012 2.99 9996 2.99	8 <u>)</u> 97 4	9996 5.0	0025 6.000 0006 6.000	3 7 0005 4 7 0005 6 7 00221 0 6 00021	8.0057 7.9945	2 005.2 2 2 8 9972 3 9 0011 18 0	142 10 9964 754 10 77 10 980 10 9966 114 10 9978	12.0035 12.1 11.9967 12 11.9967 12.5	14.0028 999 14.0084	14.994 15 15.0008 15 14.9993 16		17) 162 153 183	2		
		1.0005	0008 3 00 7291 4 77 9012 2 99 9998 2 99 9999 3 00 9999 3 00 9017 2 90	1 4	3 999 4 1 0001 4 9	977 5.977 9374 6.000	0 6.9954 6 7.001	7.9945 7.9943 7.9985 0.0014 8.0022	8 9978 9 9 8 9916 10 0	931 11.0012 007 11.0024	11 1000 12 5	957 13 5997 14 14 0005	14 9993) 16 14 9917 15	9996	142	1		
			9906 2.99 9956 2.99		<u>9957</u> 4.9 1.0013 5.0	971 6.003	6 7.0043	8.0014	8.9987 9.9 9.0029 10.0	9621 11.0044 022 11.0001	11.9965 12.5 11.9963 13	995 14.0005 002 14.0024	14 9991 15 15.0027 16	1004	1.45	1		
		1.0003					6 7.000775		3 393415 9.999	50 11 625 10 990025	12 13 29757 13.000	13 54	15 14 99792 15.9	1 10	5216			
Nors	900		2 99976 2 999	17 3 22	99945 4.99	7945 6 00096	T 000775	0073400				447 0.00727	0.006017910	1111 0 223	1001			
Aver Set		0.0005314 0.00	0017 3.00 9951 2.99	17 3 99 20 0 001 4 4 5 3	144.11 0.0022 4.002 5.0 1.9957 4.3	21808 0 nn Vila 0045 6 000 9957 5 994	0.00.96362 7.0001 5. 6.9954	6 0057 7 9942	9.0077 18.0 8.9915 3.9	122 0.054199 0. 052 11.0053 921 93.9913	12 0063 12 5 11 9855 12 5	44.7 0.0071115 131 54.0129 014 13.9867	15.0065 N 15.0065 N 14.9071 15	68359 0.247 011 9732	1981			
Aver Sad Jeans Jeans	age Dev red Value red Value	0.0005314 0.00	2 19976 2 999 19645 0 00141 9017 3 00 9951 2 99 9036 0 00 6	17 3 99 17 0.001 18 3 19 3 19 3 19 3 19 6		2188 0.00.VM4 0045 6.000 9957 5.994	0.00.96362 7.0001 5. 6.9954	0.0033404 0 0.0057 7.9942 0.0115 0	9.0077 10.0	122 0.054199 0. 052 11.0053 921 93.9913		44.7 0.0071115 131 54.0129 014 13.9867	15.0003 11 0.009 15.0003 51 14.9071 15 0.0198 0	68359 0.247 011 9732				



Record Filtering


Quickly display and report on the data needed at the moment.


Non-Normal Data

If the measurement data has a single-sided tolerance, Buddy can optionally command Minitab to generate a Goodness-of-fit test and then use the highest P value when running non-normal charts.

Prolink Charting - Charts

Create charts without the need for Minitab. These charts can be used automatically in Excel Jobs.






Prolink Charting - Statistics

A myriad of statistical calculations are available via Prolink Charting allowing the creation of robust reports.

37			4.495381			
38						
39		Min	4.491416			
40	Calculations	Max	4.506641			
41	ati	Average	4.499696			
42	E	Range	0.015225			
43	ē	Ср	0.91864			
44	0	Cpk	0.893453			
45						

Characteristic Filtering

Reduce on-screen clutter to quickly identify only the most critical characteristics.



For more information, contact us at sales@rfminc.net Resources for Manufacturing, Inc. • 3000 South Tech Blvd, Miamisburg, OH 45342 • (937) 436-4699